

SYSTEM SUPPORT DIRECTIVE

ASR9

SDR-ASR9-006

6310

System Documentation Release

UPDATE TO SSM-ASR9-012 OMIT INCORPORATION OF TI 6310.28 PAGE CHANGES

Highlights

- Clarification of SSM-ASR9-012 WSP documentation release
- Continue modifications at 34 ASR-9 WSP sites

01/23/2004

1. PURPOSE. This system documentation release (SDR) provides clarification of a previous SSM release. SSM-ASR9-012 paragraph 17 instructed the holders of the Instruction Books to update the TI 6310.28 November 2001 version with attached page changes for the Weather Systems Processor (WSP). This action would result in a technical instruction book with a WSP-only configuration and impact field personnel at facilities that are not configured for WSP. A future update to the TI 6310.28 will be issued at a later date to correct this problem.

2. DISTRIBUTION.

a. This SDR is distributed to selected offices and services within Washington headquarters, the William J. Hughes Technical Center, the Mike Monroney Aeronautical Center, regional Airway Facilities divisions, and Airway Facilities field offices having the following facilities/equipment: ASR-9

b. An electronic version and distribution report of this SDR are available on an Intranet site located at <http://aos-ext.amc.faa.gov/> under the "Technical Documentation" heading.

c. To obtain additional hard copies of this publication, contact Printing & Distribution Team, AMI-700B, at (405) 954-6892.

3. WITHDRAWALS/CANCELLATIONS. None.

4. APPLICATION. All ASR-9 facilities (WSP and non-WSP) should omit the update to TI 6310.28 associated with SSM-ASR9-012 paragraph 17. The page changes for TI 6310.28 should be kept as an attachment to the SSM-ASR9-012 in the ASR-9 SSD binder and used as a reference for WSP sites until new documentation is issued.

5. CHANGES TO RECORDED DATA. Enter this SSD number, date, chapter, and change number on the appropriate FAA Form 6032-1, Airway Facilities Modification Record.

6. ADDRESS CHANGES. Submit facility address, copy count, and additions or deletions to Carrie Batty via e-mail at Carrie.ctr.Batty@faa.gov.

DISTRIBUTION: Selected Airway Facilities Field
and Regional Offices, ZAF-605

INITIATED BY: AOS-270

01/23/2004

7. RISKS. If this change is not incorporated, multiple documentation configurations may exist and the National Airway Systems (NAS) technicians may not be able to perform procedures with an accurate ability to maintain operations.

8. STATUS ACCOUNTING. Providing your equipment is listed in the Facility/Service Equipment Profile (FSEP), the Maintenance Organization has opened a Log Equipment Modification (LEM) record in the Maintenance Management System (MMS). Upon completion of this modification, you are required to close the LEM record and change the Maintenance Action Code (MAC) to a "G" if the modification was completed or a "W" if the modification is not applicable. In the event that your equipment is not listed in the FSEP, it is your responsibility to open the LEM record upon receipt/completion of this Modification. Verify that an "N" is in the "REP COD" field to ensure that the log entry will be upwardly reportable to the national database for National MOD Tracking. The data is to be entered into the LEM as follows:

FAC/SERV: ASR9

SHORT NAME: SYS

LOC/ID: 53AC

Order No.: SDR-ASR9

Chapter: 006

Change: I

NOTE: All ASR-9 facilities (both WSP and non-WSP) must also process an LEM entry per paragraph 24 of SSM-ASR9-012.

If you have any questions, please contact Vernon J. Newte, AOS-270, at (609) 485-6518.



Richard A. Thoma
Program Director for Operational Support